


RF120VPRDC Schematic



UP=	MOTOR 2 + MOTOR 1 -
DOWN=	MOTOR 2 - MOTOR 1 +

TRUTH TABLE
K1 - UP OR DOWN
K4 - UP

****RELAYS SHOWN IN OFF CONDITION**

RF120VPRDC Pendant Diagram

